

**Tokio Marine America
Fire Protection Impairment
Notification System**



**TOKIO MARINE
AMERICA**

OPTION 1: Online Impairment Notification System

Link is available from our website at:

www.TMAmerica.com/impairments

OPTION 2: E-Mail Impairment Notification System

[impairmentdesk@tokiom.com]

OPTION 3: Hotline Impairment Notification System

(866) 247-2942

OPTION 4: FAX Impairment Notification System

(866) 372-3979



**TOKIO MARINE
AMERICA**

**Fire Protection
Impairment
Notification System**

Serviced by Global Risk Consultants



*For more information please contact us via email
tmmlosscontrol@tokiom.com*

or

Call (888) 525-2942

**Tokio Marine America's
Online Notification System**

A service of the Tokio Marine America Loss Control
Department.

Protecting our Global Community of Customers.

Fire Protection Impairment Notification System

WHAT IS A FIRE PROTECTION IMPAIRMENT?

WHENEVER A FIRE OR EXPLOSION PROTECTIVE SYSTEM IS SHUT-OFF OR TAKEN OUT OF SERVICE.

- SPRINKLER SYSTEMS
- FIRE PUMPS
- FIRE MAINS
- DETECTION & ALARM SYSTEMS
- GASEOUS SUPPRESSION



The effects of a fire or explosion without protection in service can be devastating.

Tokio Marine has enhanced our existing impairment notification program with an **online reporting system** that:

- Prompts the users with recommended precautions
- Creates a printable impairment tag
- Sends email notifications and reminders to restore the system
- Automatically tracks impairment until restored
- Restore the Impairment Online
- Eliminates the need to retain printed records to TMM review

Global Risk Consultants	
<p>Impairment Information: (UTC-08:00) Pacific Time (US & Canada)</p> <p>Impairment Start: 8/9/2014 7:00:00 AM</p> <p>Anticipated Restoration: 8/10/2014 4:30:00 PM</p> <p>Building ID: 1998 Mfg</p> <p>Scheduled or Unscheduled?: Scheduled</p> <p>Estimated Area Impaired (Sq Ft /Sq M): 10,000 - 50,000 sqft</p> <p>System Affected: Sprinkler System</p> <p>Area Description: Ceiling sprinklers are being relocated to accommodate a new duct installation. Please provide a brief explanation as to why this system is being impaired. While ducts are installed and heads relocated, this system needs to be dented.</p>	
<p>Precautions which have been taken:</p> <p><input checked="" type="checkbox"/> Site Emergency Organization Notified</p> <p><input type="checkbox"/> Hydrant Connected to Sprinkler Riser with Hose</p> <p><input checked="" type="checkbox"/> Alarm Monitoring Company Notified</p> <p><input type="checkbox"/> 24/7 Work Authorized until System Restored</p>	

ONLINE FEATURES

Input the data once, print the tags and your ready.

- Update, Extend or Even Delegate Management of an Impairment
- Access simple training videos to help use the system
- Choose your language: English, French, German, Italian, Spanish, or Portuguese
- Link is available from our website at:

www.TMAmerica.com/impairments

or

www.TMAmerica.com/losscontrol/property.aspx

- Of course, our Loss Control Engineers are still available to support you if needed.

Global Risk Consultants	
<p>WARNING:</p> <p>Fire Protection System Impaired</p> <p>Extra Precautions to Control Ignition Sources in Effect</p>	
<p>INSTRUCTIONS: After printing this impairment tag, fold in half, insert this tag into plastic sleeve and hang on the impaired device.</p>	



TMA is committed to the highest customer trust.

We exist to deliver ANSHIN (safety, security and peace of mind) to our customers by providing the highest quality services.